



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Choteau Public Schools	
Vehicle I.D. # (VIN) - Entire Number 0HVBBABM6YH303767	Model Year 2000	License # G642	Rated Capacity ***** 47
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: teton Bus Service Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Choteau Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAGCSH8SF064947	Model Year 1995	License # G645	Rated Capacity ***** 60
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: teton Bus Service Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Choteau Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAGLSH6VF073232	Model Year 1997	License # G644	Rated Capacity ***** 60
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: teton Bus Service Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Choteau Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDNB80C45VA03025	Model Year 1995	License # G641	Rated Capacity ***** 36
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: teton Bus Service Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Choteau Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBG6P1A9FV104919	Model Year 1985	License # 233	Rated Capacity ***** 30
Chassis Make Chevrolet	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Choteau Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBJG31F1Y1250314	Model Year 2001	License # G643	Rated Capacity ***** 30
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: teton Bus Service Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Choteau Public Schools	
Vehicle I.D. # (VIN) - Entire Number 8478	Model Year 1988	License # G545	Rated Capacity ***** 36
Chassis Make Chevrolet	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: teton Bus Service Inc.		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Bynum Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GBG6P1B3KV108533	Model Year 1989	License # 384	Rated Capacity ***** 36
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Fairfield Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDP880C95VA28169	Model Year 1995	License # 298	Rated Capacity ***** 48
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Fairfield Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4UZAAXBV33CL71588	Model Year 2002	License # 434	Rated Capacity ***** 58
Chassis Make Freightliner	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Fairfield Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4UZAAXBVX2CK07141	Model Year 2002	License # 412	Rated Capacity ***** 48
Chassis Make Freightliner	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Fairfield Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4UZAAXBVX3CK61195	Model Year 2002	License # 419	Rated Capacity ***** 58
Chassis Make Freightliner	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Fairfield Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4UZAAXCS15CU30127	Model Year 2004	License # 446	Rated Capacity ***** 58
Chassis Make Freightliner	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Fairfield Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4UZAABVX1CH69915	Model Year 2000	License # 396	Rated Capacity ***** 52
Chassis Make Freightliner	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Fairfield Public Schools	
Vehicle I.D. # (VIN) - Entire Number XIT88P4B26W115870	Model Year 1998	License # 350	Rated Capacity ***** 40
Chassis Make Thomas	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Power Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPB80C2TVA18861	Model Year 1996	License # 114	Rated Capacity ***** 48
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Power Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPJ75C1RVA41434	Model Year 1994	License # 123	Rated Capacity ***** 60
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Power Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBL7T1C12J512774	Model Year 2003	License # 236	Rated Capacity ***** 48
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Power Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1HVBBABP4WH627890	Model Year 1998	License # 376	Rated Capacity ***** 54
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Power Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1T88U4C2631127490	Model Year 2003	License # 416	Rated Capacity ***** 42
Chassis Make Freightliner	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Power Public Schools	
Vehicle I.D. # (VIN) - Entire Number 8542	Model Year 1986	License # 237	Rated Capacity ***** 59
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Golden Ridge Elementary	
Vehicle I.D. # (VIN) - Entire Number 2GBHG31J2K4116477	Model Year 1989	License # E623	Rated Capacity ***** 19
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Charles S Forseth		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Greenfield Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GBJ6P1PXMV103558	Model Year 1991	License # 12	Rated Capacity ***** 48
Chassis Make Chevrolet	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Greenfield Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GBL7T1C0YJ524827	Model Year 2001	License # 10	Rated Capacity ***** 48
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 50 Teton		District Name Greenfield Elementary	
Vehicle I.D. # (VIN) - Entire Number 1GBL7T1J7TJ109169	Model Year 1996	License # 11	Rated Capacity ***** 48
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date